


July 5, 1973

TO: ALL BOLENS DISTRIBUTORS, BRANCHES AND DEALERS

SUBJECT: 1055 (G-10) CHOKE CABLE

On some units, the choke cable may have been installed incorrectly on the above model tractor. This cable may have been routed underneath the heat shield. Heat from the engine exhaust pipe then may cause the choke cable to become hard to operate or function properly.

If you receive complaints, or have units in stock, check the routing of the cable and reinstall as shown in the photo. Check operation of choke plate so that a full open and closed position is obtained.



BOLENS^{DIVISION}

SERVICE BULLETIN

237

July 5, 1973

TO: ALL BOLENS DISTRIBUTORS, BRANCHES AND DEALERS
SUBJECT: 1055 (G-10) CHOKE CABLE

On some units, the choke cable may have been installed incorrectly on the above model tractor. This cable may have been routed underneath the heat shield. Heat from the engine exhaust pipe then may cause the choke cable to become hard to operate or function properly.

If you receive complaints, or have units in stock, check the routing of the cable and reinstall as shown in the photo. Check operation of choke plate so that a full open and closed position is obtained.

